

~~Discharge Day 4 2 Bottom~~

Surveyor 17. 2. 19

Received from Chief Ship Surveyor

Ferro-Concrete Aux.Sch."MOLLIETTE". Rpt. Lon. No.81543

the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

sement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also
out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points
ed in the endorsement."—Extract from Sub-Committee's Report,24/5/92.)

F I R S T E N T R Y .

This vessel appears to have been built in accordance with
the approved plans and it is submitted may be classed *A.1.
For English Channel and Coasting Service from Thames to Milford Haven",
Subject to Annual Survey",and subject to the notation "Experimental"
being made in the Register Book.

- * A.1 "For English Channel and Coasting Service from
Thames to Milford Haven".
- "Subject to Annual Survey".
- "Experimental".
- 1 Dk.F.K. 3 BH. Lloyd's A & C.P. R Q D 30'. F 23'
- Mchy.Aft.

The Certificate of Classification, to be endorsed
"Cargo battens not fitted," and the same
notation to be printed in the Register Book.

M *Pei.*
21. 2. 19

The Surveyors should be requested in future similar
cases to report the depth of the beams clear of the slab as
has been done in the case of the frames & floors,&c.

M