

433
717

Engines made at

Copu

By whom

1940

COPY.

Lloyd's Register of Shipping.



Port Copenhagen,
17th January, 1939.
23rd, January, 1940.

This is to Certify that I have
This is to Certify that I have

6 tons gross, of Copenhagen, while the vessel was lying
urveyed the steel screw motorship "CHILE", 6956 tons gross,
position and afloat at Nakskov,
f Copenhagen on the 19th of January, 1940 and subsequent da-
es when placed on pontoon at Messrs. Burmeister & Wain's Ma-
skin- og Skibsbyggeri, Copenhagen, after alleged grounding and
heavy weather at Frederikshavn on the 16th of January, 1940,
nd that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report, stating that all repairs
recommended by me have been completed to my satisfaction, and
made in the Register Book in the case of this vessel when
that I have Recommended that she be eligibt to remain as
survey has been completed, and of N.D.B. 1.40 - 114 lbs.
classified and to have record of survey 1.40 subject to anchors
arts now examined:— as part continuous survey:—
and chain cables being placed in order as found necessary on
board Main Engine:— No 3 cylinder, pistons, covers, valves
vessels arrival at Immingham.

being fit to carry engine complete with air compressor & working
& spare air receivers.
The Port cooling water pump.
The aftermost electric driven bilge & sanitary pump.
The sea connections.
The oil fuel installation for the donkey boiler.

V. Andersen

Surveyor to Lloyd's Register.

J. Langhorne

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
ted, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
ver to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its
nittees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

10m,8,38. (MADE IN ENGLAND.)

Lloyd's Register
Foundation

Damage or Repair Fee (if any).....
(per Section 29.)

75.00

Received by me,

J. Langhorne
Engineer Surveyor to

