

1

Sent to Chief Surveyors

10/6/13

Received from Chief Surveyors

VESSEL'S NAME

*St H Ondo*

Report

*Low*

No. *7576*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22)

Nature of Survey

*1st S No 3*

When due

*2.13*

Withdrawal of class

The First Special Surveys Nos. 1 & 2 were allowed by the Committee to be held by the Owners representative.

The 1st s.s. No. 3 became due in February last, and in April the Owners were informed that such an important survey as the s.s. No. 3 must be held by one of the Society's Surveyors, and they were asked to send the vessel to a port where a Surveyor was stationed, if it was desired to continue her classification.


The Owners now state they have decided not to continue the classification of the vessel.

It is submitted the vessel's class be withdrawn from the Register Book, and three dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

Withdraw class

Insert (...)

*E. B. S. M.*



© 2021

Lloyd's Register Foundation

*W 1557-0043*