

Chief Surveyors _____

Received from Chief Surveyors _____

EL'S NAME Steel S.S. "SALUDA." Report Phl. No. 3195

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Clasing Committee the endorsement to contain a succinet summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Clasing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24562.)

re of Survey _____

When due _____

255 fathoms of chain cable out of the 270 supplied have been tested by the Surveyors to the American Bureau.

2100 A.L. (Steel).

2 Dks. (Steel) and Webframes.

Cell DB 279' 1380t. MT 24' 748t. FPT 144t. APT 100t.

EK. 8 BH. Cem. A.P. P29', B122', F43'.


16. 5. 19.

The date of launch should be stated.

Detail plans not received.

In view of nearly the whole of the chain cable having been tested by the American Bureau Surveyors the notation should be A.P.

S. O.
16/5/19.



© 2020
Lloyd's Register
Foundation

W1575-0037