

COPY.

RECEIVED:- 14 FEB 1923

RECEIVED:- 21 FEB 1923

Lloyd's Register Of Shipping.

HAMBURG. 10th February 1923.

Dear Sir,

re withdrawal of class at Owners request

The steamer "FUNDUS" No. 79021 in Register Book was sunk, refloated and the necessary repairs thereto were contracted under the survey of the Germanischer Lloyd, on verbal intimation the Owner that the repairs would also require to be surveyed the Society's Surveyors, he gave no definite answer but wrote a letter which is enclosed herewith, from which it is observed he does not desire to continue the Society's class.

This is due to the difference in fees that would be charged by the Germanischer Lloyd for Surveys as compared with the Society's scale of fees.

The following are further names of vessels given in the Owners letter which he desires to have their classes withdrawn from the Society's Register Book when Surveys or Repairs on same become due.

"DISCUS"	No. 78737
"GLOBUS"	79126
"HUMUS"	79292
"MUNDUS"	79971
"OPUS"	80263
"REBUS"	80574
"SOPHUS"	80787
"TURNUS"	81024

I am, Dear Sir,
Yours faithfully,
etc.

Translation of letter referred to above:-

S.S. "FUNDUS"

Herewith I respectfully advise you that the above named steamer as well as the following vessels "DISCUS", "GLOBUS", "HUMUS", "MUNDUS", "OPUS", "REBUS", "SOPHUS", "TURNUS" have been transferred to the Germanischer Lloyd survey and therefore beg you to discontinue the further survey of these 9 ships.



© 2021

Lloyd's Register
Foundation

W1582-0107