

1

Sent to Chief Surveyors .....

Received from Chief Surveyors .....

VESSEL'S NAME "ARDENVOHR" F.E. Report Gls No. 62950

**For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/02.*)

Nature of Survey ..... When due .....

The class is subject to cargo battens being fitted in Nos. 3 and 5 holds and part of No. 1 hold.

It has been agreed that the temporary omission of ceiling under hatchways, cargo battens or hatch covers at decks other than weather decks need not be made conditions of a vessel's class.

It is accordingly submitted that in the present instance the condition of class as above be deleted, and a note inserted in the Special Reasons List, as below.

As Now, Without, etc.

*[Signature]*  
19.11.100

Insert in S.R.L (Cargo battens to be fitted in Nos. 3 and 5 holds and part of No. 1 hold at the first available opportunity).

*States note  
first*



© 2020

Lloyd's Register  
Foundation

W161-0132