

Received from Chief Ship Surveyor

3 OCT 1952

SHIP'S NAME

'BEGUM'

REPORT

Cal.

No. 15175

Outstanding Conditions of Class: Subject to permanent repairs to indented shell plating (p & s), and to set over stem and stem plating by the Special Survey.

Endorsement of Class (B) (As before ~~or None~~)

ACTION is DEFERRED for examination in dry dock after grounding surveys due: and for a Special Survey (C) which became due 12,51 by 4,53.

Nature of Present Survey: (~~Afloat and in dry dock~~) Equipment - 30 fathoms of damaged c.c. removed, 15 fathoms supplied.

Special Features:

Is Interim Certificate in order (Yes-~~No-None~~)

Items Outstanding: (If any for S.S. or A.S.)

Work to be completed by: 4,53.

Recommendation: SUBJECT as above, and to 15 fathoms of chain cable being supplied at the earliest opportunity, but ACTION be DEFERRED for examination in dry dock after grounding and for a Special Survey by 4,53.

As Now. Subject.

ENDORSEMENT OF CLASS (B).
Shell plate No. 4 (p.s.) in 1st below sheerstrake indented.

W.O.T.
2.10.52

IN S.R.L.
Drydocking (grounding).



© 2021

Lloyd's Register Foundation

W1624-0002