

Received from Chief Ship Surveyor

NAME "BANNROSE" REPORT Bel. No. 15514

standing Conditions of Class: Subject to the steering rod guides and rudder head lignum vitae blocks being renewed at the next drydocking and the starboard anchor being verified and 15 fathoms of chain cable being supplied at the earliest opportunity.

ACTION is DEFERRED for Special Survey.

sement of Class (B) (As before ~~or None~~)

ys due: Postponement of Special Survey (C) (due 9,52) until 9,53 previously approved subject to satisfactory G.E. in drydock by the end of 1952.

e of Present Survey: (Afloat and in dry dock)

General Examination as above.

al Features: Due to the cost of repairs required for S.S. and conditions of trade for a ship of this tonnage the Owner has decided to sell this ship for scrap.

terim Certificate in order (Yes-No-None)

Outstanding: (If any for S.S. or ~~A.S.~~)

~~None~~ All items.

to be completed by:

mendation:

SUBMITTED record of docking 2,53 be assigned, but further ACTION be DEFERRED pending information regarding disposal of the ship.

2,53 Bel.

ENDORSEMENT OF CLASS (B).
Set up bottom plating.

ABM.
9.3.53.



© 2021

Lloyd's Register
Foundation

W1624-0017