

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen, London

Telephone: ROYal 3551 (6 Lines)

1st May, 1953.

Dear Sirs,

Steamer "BRITISH COLONEL"

I have to acquaint you the Committee have had before them a report received from the Society's Surveyor at Alexandria of a survey held in March last, from which it is noted that the forward half H.P. turbine flexible coupling was found to be worn.

As no spares were available at that time it was recommended that the above item should be renewed on completion of the present voyage to a North Sea port, and the Committee have accordingly continued the vessel's class subject to this matter receiving attention at that time.

Yours faithfully,

Assistant Clerk to the
Classification Committee.

The British Tanker Co., Ltd.,
Britannic House,
Finsbury Circus,
LONDON, E.C.2.



© 2021

Lloyd's Register
Foundation

W1630-0119

sn. (S)
JAC