

55/1/21

15 JAN 1955

No. 1781

NONE.

ACTION is DEFERRED for Special Survey by 11,54.

A further proposal to postpone completion of this survey until February next approved - see letter dated 17.12.54.

Repairs to rudder trunk plating.

Interim Certificate in order (Yes-No-None) gutted by fire in Singapore Roads on 25th December - see endorsement dated 31.12.54.

FOR PORTION OF SURVEY HELD:- See H.Kg. Rpt.No.12092.

IT IS SUBMITTED ACTION be DEFERRED pending further information regarding disposal of this ship.

Wavy bottom plates in 'A' & 'B' strakes (p.s.) in way of E.R. to be kept under observation.

S.S. PART HELD.

© 2021

Lloyd's Register

Pub^s still awaiting info as to whether this ship is
C.F.L.