

Ceiling in Holds, thickness and material

2 1/2 O.P. ✓

Cargo Battens, thickness, material

Ref. to

Thickness of Hatches

No. 6290

Port

Sunderland

(Received at London Office,.....)

RECEIVED

Date

5th Oct - 7 OCT 1948

We

request that the

Motor Vessels

for

A. P. MOLLER

by

Bartram & Sons Ltd. Sunderland

of

8740

Tons.

Length,

430.0

breadth,

58.9

depth,

38.2

may be Specially Surveyed while building (100 A. / Class under Special Survey)

If for a particular term or class, state the same

We

hereby engage to pay the established Special Survey Fees or any variation therefrom which has been duly notified and, in addition, any travelling and other expenses which may be incurred by the Surveyors in connection with the survey.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

No. 927/8 in Builder's Yard.

Manufacturers of Engines

M. E. Mann Eng Co Ltd. Wallsend

Ditto

of Boilers

Signature

FOR AND ON BEHALF OF

BARTRAM and SONS LTD

©2021

To the Secretary,

Lloyd's Register of Shipping,

71, Fenchurch Street, London, E.C.3.

NOTE.—To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:—

"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements,"

Authd
C/P 13/10

in deep tanks have been examined

W1639-0221