

M. BERENDT,
Ingenieur.
Engineer Surveyor
to Lloyd's Register of British
and Foreign Shipping.

Telegramm-Adresse:
Ingbert-Hamburg.
Fernsprecher Amt I, 9599.

H.

Hamburg, 26th June 1910.
Admiralitätsstrasse 52.

LLOYDS REGISTER,
LONDON.

REC^d 28 JUN 1910
ANS^d

Sir,

I have to inform you that
by a slip of the pen an error has
occurred in the Report N^o 11509,
First Entry of Machinery of the
steamer "Penshurst", inasmuch
that the diameter of the H. P. cylin-
der has been stated to be $28\frac{3}{4}$ ",
whereas it really is $28\frac{3}{8}$ ".

I beg you will excuse this
mistake and arrange for its cor-
recture in the Register Book.

I am,

Sir,

Yours obedient Servant.

M. Berendt.

The Secretary,
Lloyd's Register
London.



© 2020

Lloyd's Register
Foundation

Referred to the Chief Engineer Surveyor.

cd
JUN 28 1910

For Mr. White
& Mr. Manley.

note.

ARR



© 2020

Lloyd's Register
Foundation