

Engine Room ...  
PAGE FOR FEES...  
434.00  
218.21

side to top of keel )  
Quarter Deck )

Chief Ship Surveyor 2/8/12

Received from Chief Ship Surveyor \_\_\_\_\_

NAME St J's "Wheatlands" Rpt. Out No. 2/83

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey First entry

It is submitted the Glasgow Surveyors be informed that this vessel was provided to their port where her machinery is to be fitted, and that to complete the survey on the hull, the engine & boiler casings require to be rickled up. They should be requested to give the care the necessary attention & on completion of the work to forward a report on form 8 with a view to the classification of the vessel.

Dr. J.S. 21/8/12

AT 2/8/12  
2/8/12  
C. C. C.



© 2020  
Lloyd's Register  
Foundation

Dry Dock  
No. of Deck  
No. of Tier  
Round Dk. Ber  
Inches in  
4"  
4"  
5 3/4"  
6 1/2"  
5 1/2"  
4 1/2"  
(Arm s  
4"  
Inches Incl  
Ship in S  
16 1/2"  
5 1/2"  
5"  
3"  
3 1/2"  
3"  
62  
3 1/2"  
3 1/2"  
11 1/2"  
2 1/2"  
3 1/2"  
3 1/2"  
3 1/2"  
3 1/2"  
3 1/2"

WEB-FRAMES, In Fore Body, No. and spacing one  
Deck. Material and thickness P. Pine  
\* If Iron or Steel Deck, state if whole or part, and