

20, 11, 21.

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME STEEL T. S. "EMPRESS of CANADA" Report GLS No. 41917

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey _____

When due _____

(see)

✱ 100 A1, Shelter D^k with Freeboard.

4 D^{K5} (see) & Shelter D^k (see pt ws)


Cell AB. 530' 3020t. Fresh Water Tanks in way of Tunnels 96' 560t. FPT. 109t Apr. 223t.

FK. 9BH to Shelter D^k + Collision B.H. to Forecastle D^k. pt Gen. Lloyds A&CP.

B & F 529' on Shelter D^k. Promenade D^k. 405'.

Date of Build 5.22.

W166-0014



Lloyd's Register
Foundation

105.22