

4 E

Engineer Surveyor

Received from Chief Engineer Surveyor

NAME "KIA-WØ".

Rpt. L.A.

No. 5949.

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report. 24/5/92.)

REPAIRS TO ~~ENGINES AND BOILERS~~ DUE TO DAMAGE THROUGH GROUNDING.

Port propeller repaired.

It is submitted the vessel is eligible to remain as classed without fresh record.



© 2021 Lloyd's Register Foundation

7.5.38.

W185-0045

carrying full cargo.