

Bronze Liners, thickness in way of bushes as per Rule as fitted  
Thickness between bushes as per rule as fitted

13/8

Enquiries  
Ref. No.

Made by *Atl. Atlas Steel Skm*

*Fredrikstad Mek. Verk. No. 255*

*Skm. Reports Nos 3222 & 3231*

30

62  
34  
65

It is submitted that ~~this~~ <sup>these</sup> Report~~s~~ <sup>sent</sup> be returned to  
the *O.S.O.* Surveyors for their guidance and  
for completion.

*Copies of Rpts  
sent 7/5/30*



Date

*[Signature]*

© 2019

*15/30*  
Lloyd's Register  
Foundation

W194-0063

Are all Sea Connections fitted direct on the skin of the ship

Are they fixed sufficiently high on the ship's side to be seen without lifting the platform plates  
Are the Overboard Discharges a