

7.12.25. *HAMPHOLM - Name of vessel*
broken

"S"

E E EASTERN TELEGRAPH COMPANY.

age Form 5)



HAMPHOLM

BACZO - stern post
EHBUX - necessary
EHSEX - part (of)
EGDUF - in
FLIGS - one
EDPOF - can
EHKYS - only
EDMAX - be


REPLY TO THIS
Via Eastern

EGVIT - manufactured
EGDUF - in
TRANSVAAL

ECVOF - and
EDRAC - cannot
EDMAX - be
EDSGO - carried
EHJYR - on account of
RAILWAY BRIDGES
ECVOF - and
MOTOR TRANSPORT IMPOSSIBLE
EHJYR - on account of
BAD ROADS

BACZO - stern post
EDOMP - broken
ECTAZ - above
EHLFY - original
EJPUC - scarph
EHAPU - my recommendations
THEREFORE

FLIGS - one
EJPUC - scarph
EDNUF - between
FLUIX - number
FLIHR - two
ECVOF - and
FLILC - three
AZSEC - rudder gudgeons
EFOBI - from
EKHZE - top
ECVOF - and
FLIGS - one
EJPUC - scarph
EDNUF - between
FLIHR - two
EGUHM - lower
AZSEC - rudder gudgeons
EDWOL - consider
EKENX - this
DOKGE - permanent repairs
EKBAM - subject to Committee's approval
EBNOS - cable reply, matter very urgent.



© 2019

Lloyd's Register
Foundation

W197-0216.1