

HAMPHOLM consider efficient scarphs  
*in cast steel stem frame*  
cannot be made/ and that you should reconsider case  
with view to temporary repairs by means of riveted  
clamps, or in other way to entitle vessel to proceed

Stop *bric up section of channels  
with jack plates stop.*



© 2019

Lloyd's Register  
Foundation

W197-0216