

F.E.

Received by Chief Ship Surveyor 1. 1. 14

Received from Chief Ship Surveyor

VESSEL'S NAME Shells "Mottisfont" Rpt. SL No. 25955

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


Transverse No. 82.37Depth "d" 24.95Framing: Table No. 3 page 16. Description Channels as appinedLongitudinal No. 31993Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{10.62}{1}$ ~~Shells~~ Deck Sheerstrake as per Rule.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A-1. (Steel) Shells Deck with freeboard," as recommended. The Summer freeboard of 3' 7½" from centre of to top of statutory deck line at upper deck, now marked on vessel's sides, to be inserted in the classification certificate recorded in the Register Book, and further, the remaining free as shown on the accompanying verification form to be inserted certificate of classification.

100A-1. (Steel) Shells Dk with freeboard
1 Dk (Stl) & Shells Dk (Stl)

LB = 136' a 136' a 50B 46' f 163' 12706. FPT 11564

FK. 634. Cam. Drgs a+cp.



© 2019

Lloyd's Register
Foundation

W200-0135