

Sent to Chief Surveyors 1-3-38

Received from Chief Surveyors _____

VESSEL'S NAME s.s. Thode Hagelund Report hwc No. 95396

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey Major repairs When due —

The class is subject to the
core of the thrust shaft
being examined.

This will be done on arrival
in Europe from the Plate or on
return to New York from Europe
in April.

Submitted action be
deferred.

W.A. 1/3/38



© 2020

Lloyd's Register
Foundation

W222-0050