

2
 Recd
 Sent to Chief Surveyors 11. 1. 37

Received from Chief Surveyors

VESSEL'S NAME *SM SC THODE FAGELUND* Report *N. YK* No. *37220*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

2nd No. *1* SURVEY PARTLY HELD.

When due *9. 36* When proposed to be completed *not stated.*

Portion of Survey held, &c.

To complete the Survey:— See Report.
 Subject to order plates (p/s) E.W 6-36 being specially examined at next dry docking.

Screen bulkhead aft of boiler to be permanently replaced when the vessel is reboilered & fidley plating to be repaired. (Corroded)

S.R.L.:— Insert after bulkhead & fidley casing.

See also Special endorsement

www-0088

Lloyd's Register
 Foundation
 12. 1. 37