



9 JAN 1937

"THODE FAGELUND"

It is submitted the Owners be informed that the Society propose to carry out a complete investigation of this case when samples of the defective boiler plating are available, with a view to ascertaining the cause of the trouble.

It is submitted the New York Office be informed that at a later stage samples of the defective materials will be subjected to a full investigation with a view to ascertaining the cause of the trouble.. If a piece of the material containing cracks is available now, it should be forwarded to this Office. A report of the water analysis is awaited.

  
  
19.1.37.



© 2020

Lloyd's Register  
Foundation

W222-0091