

W232-0048

4 E

13 APR 1942

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

Aghios Spyridon

Rpt.

No.

No.

100183

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32.)

of Survey

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH *Cause not stated*

The machinery has been generally examined satisfactorily. Circulating and air pump casing renewed. Condenser tubes plates renewed. Dynamometer & steering engine painted & electrical installation repaired & tested

partly held 6.41. Now completed A number of tubes renewed

It is submitted that this vessel is eligible for THE RECORD.

B.S. 6.41 N.P. 1801b.

1.42 Examined L.R. for 12 months

Without Special Condition

© 2021



Lloyd's Register Foundation

TRMS  
13.4.42