

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report May 20th 1924 When handed in at Local Office May 20th 1924 Port of NEWCASTLE-ON-TYNE

No. in Reg. Book 40510 Survey held at North Shields Date, First Survey Last Survey May 16th 1924

on the Wood, Iron or Steel Se Pacific Trader Master

TONNAGE:— Built at Sunderland By whom W. Doyford & Son Ltd When 1924

GROSS 6100 Owners Furness, Withy & Co Ltd Port belonging to London

UNDER DEK 5257 Owners' Address Managers

NET (if not already recorded in Appendix to Register Book)

Surveyed Afloat or in Dry Dock? In Dry Dock Name of Dock Smiths Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet; } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

total capacity tons. FPT tons; APT tons; MT feet tons. }

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as ft. ins. painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Docking

Vessel placed in dry dock. Bottom and rudder cleaned, examined & found in order afterwards recoated.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	
Decks	State if Tanks have been examined inside
Caulking of Decks	State if Tanks now tested
Waterways	Bulkheads
Coamings	Ceiling
Beams & Fastenings	Cement or Asphalt (State which.)
Outside Plating	Rudder
Caulking of ditto	Steering gear and its connections
Rivets	Windlass
Breasthooks & Crutches	Have Pumps now been examined and found efficient?
Transoms	Have Steam Valves now been examined and found efficient?
Frames	Have Watertight Doors now been examined and found efficient?
Reverse Frames	Have Ventilators and their Coamings been examined and found efficient?
Floors	
Keelsons	
Stringers	
Inner Bottom Plating	
	Dblng. Plates under Sounding Pipes
	Engine Room Skylights
	Coal Bunkers, Open'gs, Lids, &c.
	Scuppers
	Cargo Hatchways
	Hatches
	Planking of Wood Vessels
	Caulking ditto
	Treenails ditto
	Breasthooks & Stemson ditto
	Transoms, Pointers, & Crutches ditto
	Timbers of Frame at openings ditto
	Ditto ditto at other places ditto
	Stringers, Clamps & Shelves ditto
	Salting ditto (State if examined.)
	Copper, or Y.M. of Wood Vessels (State if on Feet.) When put on, Month Year
	Boats
	Masts, Yards, &c.
	Condition, how ascertained (State if wedges removed)
	Sails
	Equipment letter
	Anchors, No. of
	Cables (State if now ranged)
	length (on board) size
	Rule length size
	Hawser & Warps
	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

This report is forwarded for the information of the Committee

Survey Fee (per Section 20)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	:	:	10
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	10

Surveyor to Lloyd's Register of Shipping. J. H. Matthews

Committee's Minute FRI. MAY. 23 1924

Character Assigned See minute on 16 report

Water Capacity Tons. 120
126
614
996

Visits 90



Is Certificate required? If so, to be sent to

W234-0044