

T.S.M. "MATAFELE".

Hong Kong Report No. 8211.

Messrs. Lancashire Dynamo & Crypto Ltd.

The test certificate of the 6 H.P., 110 volts, 1450 r.p.m., motor number 59X926 indicates that the high voltage (dielectric) test was carried out at 1500 volts instead of 2000 volts as required by Appendix 2, Clause 6, of the Rules for Electrical Equipment.


As the motor is of small size and 110 volt rating it might be accepted in this instance.

IT IS SUBMITTED the Firm be informed it is noted the test certificate of the 6 H.P., 110 volt, 1450 r.p.m. motor number 59X926 indicates a high voltage test of 1500. This is not in accordance with the Society's Rules for Electrical Equipment or the B.S. standards, but no exception will be taken in this instance.

It should be pointed out that in all future cases the high voltage test is to comply with Appendix 2, Clause 6, of the Rules for Electrical Equipment.

L 22/12

Row



20th December, 1938.

W252-0048