

11

53 JUL 1941

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME Bennew's Rpt. Hkg No. _____


Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.

Survey Docking
 The Hong Kong Surveyors report this vessel placed in dry dock, bottom cleaned and coated, ~~repairs or renewals~~ of rudder pintle and minor repairs effected to be repaired Kul.

It is submitted the vessel appears worthy to remain as classed with record of survey 3,41 as recommended.

100 A1
 3,41 Hkg.



Side Plating	Good	Cement or Asphalt (State which.)	Good	Oil Bunkers	-	Condition, h
				Scuppers	Good	(State i
				Cargo Hatchways	#	Yard