

S.R. List Nothing has been done at this time towards effect

1m,10,40.

1

20 MAY 1941

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME DOMINO Report LIV. No. 115989^A

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DOCKING. When due.....

Subject to indented plating etc N^o. 4 from forward in
2nd stake below sheer (p.s.) being repaired at the
Owners convenience

Wag
20.5.41



© 2021

Lloyd's Register
Foundation

W26-005

Survey Fee (per Section 29)£

Fees applied for,

forward to ...