

COPY.

# Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

W272-0-005618

ENCLOSURE.

23rd December, 1925.

Dear Sir,

I have to acknowledge the receipt of your cablegram in regard to the steamer "LORD STRATHCONA", as follows:-

H.

LORD STRATHCONA- Vessel's name.  
DYPAN - Owners wish class retained  
EBOFD - cable particulars  
EKOTA - what is necessary to be done now.

and in confirmation of my reply, a copy of which is enclosed herewith, I have to inform you that in order to entitle the vessel to have her class reinstated in the Register Book the Special Survey N°2 must be completed, all necessary repairs carried out and the Boiler Survey held. To complete the Special Survey the N°3 double bottom tank, the after peak tank topside tanks require to be scaled and spar placed in order. The following repairs by the Society's Surveyors at Newport in

Shell plates to renew:- Port :- E.1.J.  
Starboard. E.1.F.  
Shell plates to remove fair and refit.  
Port:- F.1. F.2. H.1. H.12. J.2. J.3.  
Starb. F.2.G.1.H.1.H.2. J.2. J.4. J.5.  
Shell plates to be faired in place.  
Port. D.1.G.1. H.2.H.3.H.4.K.1.  
Starb. F.10.G.10. M.1.M.2.

© 2021

Lloyd's Register  
Foundation



COPY.

2. s.s. "LORD STRATHCONA".

Some odd shell rivets require to be renewed, the cement box in the fore peak to be renewed, tanks in way of repairs to be tested on completion of repairs, frames (transverse and longitudinal) to be dealt with as found necessary. The repairs on port side amidships require to be dealt with before the vessel loads cargo.

I may add your account has been debited with the sum of 11s/3d, the cost of my message to you.

I am, Dear Sir,

Yours faithfully,

Assistant to the Secretary.

*Copy to Mr. Ascham*

T. Moon Esq.,

HALIFAX, N.S.,



© 2021

Lloyd's Register  
Foundation

W272-0005 (2/2)