

2500, 12, 10.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Stl & M/V 'ELSA'* Report *Sls* No. *47941*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 21.5.99.)

Nature of Survey *1st Entry* When due *Revised* Rule

✠ 100 A.1. (Steel). Carrying Petroleum in Bulk
2 D^{ks} (Stl). & Web frames. Longitudinal framing
Cell D.B. & E 64' 195t, D.T. & 41' 540t, F.P.T. 66t, A.P.T. 34t.
F.K. 14 B.H. (10 B.H. to upper D^k, 4 B.H. to 2nd D^k) Lloyd's A.C.P.
P 85', B 27', F 45'. Machinery aft



© 2000

Lloyd's Register
Foundation

W273 -0081

Longitudinal

Bridge Deck ...

Transverse

162x40

Hanger

162x40

Hanger