

(Received at London Office 7.6.39)

No. LA 6611

REPORT OF SURVEY FOR REPAIRS, &c.

of writing Report... 19... When handed in at Local Office... 19... Port of GRAN

Survey held at on the Wood, Iron or Steel Date, First Survey "SUZY" Last Survey 2/19 19...
Built at Pt. Glasgow By whom Clyde S.B. & E.C. W When 1907 2
Owners B. Athanasiades Owners' Address (if not already recorded in Appendix to Register Book)
Managers A. Davaris Port belonging to Piraeus

Report, No. 9716 Port Msl
Name of Dock _____ Destined Voyage _____
DBorDBa _____ feet; uE&B _____ feet; f _____ feet
Capacity _____ tons. FPT _____ tons; APT _____ tons; MT _____ tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)
CHARACTER: +100 A1
Date of last Survey and of Periodical Surveys: 11.38
Machinery and Boiler Surveys (including date of N.B., if any): +LMC 4.37
BS 11.38
OG 10.38

Society's Freeboard (if assigned) as painted on Ship and now verified _____ ft. _____ ins.

Was a damage report made by anyone else? If so, by whom? _____

LIBRS, OR EXAMINATION AS PER RULE, FOR _____

DESCRIPTION OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Paired or Repaired								
Paired or Repaired in place								

GENERAL CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Deck of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Plating	Cement or Asphalt	Oil Bunkers	When fitted, Month _____ Year _____
Fastenings	Rudder	Scuppers	Boats
Windlass	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
Have pumps been examined and found efficient?	Windlass	Hatches	Condition, how ascertained (State if wedges removed)
Have Sluice Valves been examined and found efficient?	Have Ventilators and their Coamings been examined and found efficient?	Planking	Equipment letter _____
Have Watertight Doors been examined and found efficient?	Air and Sounding Pipes	Caulking	Anchors, No. of _____
Have Tanks been examined internally?	Doubling Plates under Sounding Pipes	Treenails	Cables (State if now ranged)
Have Tanks been tested?		Breasthooks & Stemson	length _____ mean diamr. _____ (on board)
		Transoms, Pointers & Crutches	Rule length _____ size _____
		Timbers of Frame at openings	Chain Locker
		" " at other places	Hawsers & Warps
		Stringers, Clamps & Shelves	Standing and Running Rigging
		Salting (State if examined.)	Sails

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)	£	Fees applied for	19
Special Damage or Repair Fee (if any) (per Sec. 29)	£	Received by me	18
Printing Expenses (if chargeable)	£		
Surveyor's Fee (if any)	£		

Committee's Minute
Character Assigned W. A. 9/6/39
FRI 9 JUN 1939
Deferred for 1 mo.
Surveyor to Lloyd's Register of Shipping
Lloyd's Register Foundation
W 281-0095