

12 DEC 1939 1

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME _____

RUBAAN

Rpt. CFF.

No. 53194

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE.

Signature of Surveyor _____

Damage through heavy weather (LIV. RPT. N° 113260) + by striking submerged object (LIV. RPT. N° 113316).

now repaired as follows:-

	Shell Plates	Main Frames	R Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:-

Vessel placed in dry-dock, bottom coated, a number of forward bottom rivets renewed and minor repairs effected.

It is submitted the vessel is worthy to remain as classed with record of Survey 11-39.

100 A.1.

11-39. CFF.

Delete from S.R.L.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

Lloyd's Register Foundation

W289-0140