

ived by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SEL'S NAME "RUBAAN".

Rpt. Cff.

No. 53194.

he remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


ture of Survey

WEATHER DAMAGE & WEAR AND TEAR.

Damage repairs:- L.P. piston rod machined; bushes renewed-bottom-
end brasses remetalled; general service pump repaired

Wear and tear repairs:- H.P. piston rod renewed.

It is submitted the vessel is eligible to remain as classed without
record of Survey as recommended.



© 2020

Lloyd's Register
Foundation

9.12.39.

W289-0142