

1638-04
76-77
GARDINER & CO.

14 St. Vincent Place,
GLASGOW, 26th May, 1915.

rs Ayrshire Dockyard Co. Ltd.,
I r v i n e.


Sirs,

Nos. 445 and 446.

I have your favour of the 24th inst. for which I
much obliged, and refer to conversation regarding the tween
bulkhead in the fore part of No. 3 hold in above steamers.
stated it will not suit our trade to have the deep tank
head carried up to the weather-deck. We would prefer that
bulkhead should stop at the 'tween decks as it will suit our
le much better, and we shall take it kind if you will arrange
Lloyds to have this done. I may state that in the last
e steamers we had built this bulkhead was stopped at the
en decks and the 'tween decks left clear right fore and aft
the stokehold bulkhead to the after deck bulkhead.

Your kind attention to this will oblige.

Yours truly,
(Sgd) John McKenzie.



© 2021

Lloyd's Register
Foundation

W293-0115

Poop Deck Stringer Plate, breadth & thickness

Angle on ditto

or in D	
Inches.	No.
9 1/2	No.
6 1/2	No.
lge Dk.	
per Dk.	
	In
	Si
	S
acing	8 1/2
"Plates	12
"Bds	2
"	2
	In
	in S
bove	✓
Plate	✓
	✓
	✓
	✓
	✓
	✓
gth...	✓
length	✓
gle...	✓
	✓
length	✓
gle...	✓
	✓
gth...	✓
le...	✓
kness	✓
idge)	✓
kness	✓
idge)	✓
ge)...	✓
ys...	✓
lng.	✓
	✓
	✓
ckness	✓
	✓
lng.	✓
ckness	✓
	✓
	✓
late.)	✓
kness)	✓
hways	✓