



Others are slightly damaged  
(striking an obstruction)

Subject to 2 propeller blades  
being dealt with at  
first opportunity.

Also Subject  
as per endorsement  
31.12.41

21/3/42

© 2020

Lloyd's Register  
Foundation