

Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and
ing detailed in the body of the report, should be briefly summarised at the end of the report. State also the
initials of any letters respecting this case.

cases where the Surveyor has not made a special damage report he is required to

of Surveyors

Received from Chief Surveyors

S NAME

EMPIRE BUFFALO or EGLANTINE Report MOB No. 1703

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - (Extract from Sub-Committee's Report, 24/5/92.)

FOR CLASSIFICATION.

No. 3

SURVEY, PARTLY HELD. & PART 1st ENTRY

When proposed to be completed

Survey held, &c.

Noted

20.11.40

class with fld

Insert in SRL:- Exd 6.40. for 6 mos.

The Surveyors should be informed it is noted the Special Survey referred to as a S.S. No 3 but if when the scrapings were ascertained from the ship, the shell plating was drilled as required for a 2nd S.S. No 3 a corresponding notation could be assigned. They should also whether this can be recommended.

t boiler was examined internally and found to be clean and in good condition. The two
lers were examined under steam and found to be sound and tight and in apparent good c

© 2020

630-0076