

Surveyors 20.3.34

Received from Chief Surveyors

NAME St. Louis "IROQUOIS" Report 7.05 No. 4287

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

Damage

When due *the 2nd SS. No 3* became due *5.33* *the proposal*
to carry out same within the year of grace has been
agreed to.

Plate in centre strake of trunk top to be renewed at
next special survey.

Welded plates in C or G strakes, starboard side to be examined
at next dry docking.



© 2021

Lloyd's Register
Foundation

21.3.34

W309-007
F500-603M