

offered his services for this purpose, and why they were declined

... a damage report made by anyone else? If so, by whom?

16 AUG 1940

Not sunk

by damages by aircraft



© 2020

Lloyd's Register
Foundation

W324-0107

... the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms.?

Please attach
Deferred reports



© 2020

Lloyd's Register
Foundation