

W329-0002

DUTCH TANKER
EXAMINED 2-40 - 12 MOS. POSTPONEMENT.

Received from Chief Surveyors _____

Presented to Chief Surveyors _____

VESSEL'S NAME

APOLLONIA

Report GLS.

No. 62643

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1ST S.S. No.

2

due 7-39

PARTLY HELD

ADVANCED BY SOME
REPAIRS EFFECTED.
DOCKING SURVEY ALSO HELD.

When proposed to be completed

To complete the S.S.:


Pitted bottom shell plates C3.4+5 and D3+4 (P+S)
require to be renewed before 28-2-41 and
worn lengths of chain cable, worn to Rule limit, require
to be renewed at the earliest opportunity.

Wals

7.8.40

Note

It is stated the chain cables are on
order & will be placed on board as
soon as possible



© 2020

Lloyd's Register
Foundation
S.S. PART HELD
RPS.