

Extends up to...

Margin Plate depth (excl. of flange) and
thickness ... (1.25) ...

Stl. T.S. "BEAVERDALE"

Rpt. Nwe. No 87336.

The Surveyor should be requested to state
the diameter of rivets through frame & shell
plating amidships also the lengths of the
double bottom & deep water ballast tanks

SJR 10-2-28

Lloyd's Register
Foundation

W336-0013

Height of Brackets at side above
base line at toe of frame

Spacing
or [.....]
every foot