

Date of writing Report 18th Oct 1924 When handed in at Local Office 18th Oct 1924 Port of Belfast

No. in Survey held at Belfast Date, First Survey 14th October Last Survey 15th October 1924

Leg. Book. on the Wood, Iron or Steel Twin Screw ORAMA Master

TONNAGE:— Built at Barrow By whom Vickers Ltd. When 1924

GROSS 20000 Owners Orient Steam Nav Co Ltd. Port belonging to Barrow.

UNDER DK. 1650 Owners' Address Managers

NET (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Name of Dock Thompson Destined Voyage Trials.

WB=CellDBorDBa feet; uE&B feet; f feet; Particulars of Classification (which must be inserted

total capacity tons. FPT tons; APT tons; MT feet tons. precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port

(Periodical surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

Now done.

Vessel placed in dry dock bottom examined throughout cleaned and painted, rudder and pintles examined and found good.

Vessel proceeding to the Clyde for her official trials

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	State if Tanks now tested	Engine Room Skylights	(State if on Feet.)
Caulking of Decks	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Waterways	Ceiling	Scuppers	Boats
Coatings	Cement or Asphalt (State which.)	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	Rudder	Hatches	Condition, how ascertained
Outside Plating	Steering gear and its connections	Planking of Wood Vessels	(State if wedges removed)
Caulking of ditto	Windlass	Caulking ditto	Sails
Rivets	Have Pumps, now been examined and found efficient?	Treenails ditto	Equipment letter
Breasthooks & Crutches	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	Anchors, No. of
Transoms	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Frames	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	„ length size
Reverse Frames		Ditto ditto at other places ditto	„ Ruls length size
Floors		Stringers, Clamps & Shelves ditto	Hawser & Warps
Keelsons		Salting ditto	Standing & Running Rigging
Stringers		(State if examined.)	
Inner Bottom Plating			

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—“to remain as now classed in the Register Book without fresh record of Survey,” “to remain as classed and to have record of survey, 1,15,” or “to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and pnd15, &c.”

This vessel so far as seen is in good and efficient condition and worthy of the class contemplated.

Survey Fee (per Section 29)	£	Fees applied for.	19.
Special Damage or Repair Fee (if any) (per Sec. 29)	£	Received by me.	19.
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Committee's Minute

Character Assigned

DOES. 4 NOV 1924

See Minute on F.C. report

W348-0015

W348-0010

Surveyor to Lloyd's Register of Shipping.

© 2020

Lloyd's Register Foundation