

sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Tw. Sc. M.S. "PACIFIC COAST" Report Gls No. 55801

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor _____ First Entry _____ When due ----

✱ 100A1 with freeboard

1 Dk & Shelter Dk

Cell DB 196' 347t, FPT 116t, APT 56t

FK, 4 HH (Coll HH to Shelter Dk 3 HH to 2nd Dk), Cem., Lloyd's A & CP

B 37', F 32'

Machy. aft

7H
hatched



© 2020

Lloyd's Register
Foundation

W350-0033



[Handwritten signatures and dates]
6.6.35