

REPAIRS, OR EXAMINATION AS PER RULE, FOR

This vessel was placed on dry dock on May 2nd, 1933, for the purpose of

to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

M. S. CHARLES PRATT

Report

N. Ns

No. 4758

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report 24/6/92.)

2<sup>nd</sup> No. 1

SURVEY PARTLY HELD.

Condition

When due

8.32

When proposed to be completed

not stated


Reason of Survey held, &c.,

To complete the Survey:— See N. YK Rpt 34408.

RETAIN

N.B.

25.7.33



See Special endorsement.



© 2020

Lloyd's Register Foundation

W373-0148

to remain as now classed in the Register Book without fresh record of Survey, "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."