



Lloyd's Register of Shipping,

55, Fawcett Street,

Sunderland, 25th May, 1940.

RETAIN
MAY 1940
WOKINGHAM

Dear Sir,

reference

We regret to inform you that Sunderland Report No. 32840 for the steamer "CONFIELD" should have stated that no direction finding equipment was fitted on the vessel and that the entry D.F. against the vessel in the Register Book should therefore be deleted.

Further the engine builders are stated in the Register Book to be N.E. Marine Eng.Co. (1938), Ltd., Sld. whereas the engines were actually built at Wallsend.

We are, Dear Sir,

Yours faithfully,
THE SURVEYORS,
PER:

The Secretary,

LONDON.



© 2020

Lloyd's Register
Foundation

W373-0204

W373-0206

Delete D.F.
L.Y.

20.5.40

28 MAY 1940

H
CO
R

F. G. P. R. S. L.

RECEIVED
MAY 28 1940

WATER



© 2020

Lloyd's Register
Foundation



PHONE : S