

Received from Chief Surveyors

Steel S.S. 'DIPLOMAT'

Report

90

No. 41392

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24592.)

When due

RETAIN

Separate endorsement regarding date of build attached to report on
'PAMELA'

✱ 100-A-1. (Steel)

2 Dks (Steel) 3rd Dk (Steel) in No. 1 Hold

11 Dk 422' 1554t, 11 Ta 38' 1324t, FPT 101t, APT 49t

Ek, 9Bk, Cem, Plyds Av CP, P54' B188' F51'

M

7.10.24



© 2021

Lloyd's Register
Foundation

W382-0021