

Chief Surveyors.....

Received from Chief Surveyors.....

'S NAME "DAPHNE" Report Gls No. 62881

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Survey DOCKING When due

The 5th Special Survey No. 2 became due 5.40.

The year of grace has been granted, subject to D.B. under boilers being repaired.

The class is subject to indented shell plates F.8 and 9 and G.9 and framing in way (s.s.) being dealt with at the Owners' convenience, repairs to tank top plating under boilers being effected at the first available opportunity and double bottom tank under boilers not being used as a tank until repaired and bulwark rail bar and stays abreast No. 4 hatch (p.s.) being dealt with at the first opportunity.

Delete from S.R.L

Rudder gudgeons.
Amend as regards B.R. tank



© 2021

Lloyd's Register
Foundation

W382-0175