

Line No. 2697 Made by Richardson, Mergantz & Co.

W. Pickersgill & Son, No. 241

Report No. 17900

It is submitted that a copy of this Report be
forwarded to the Sd. Surveyors for their
guidance and for completion.

Date

17/11/39

W 382 - 0215

© 2021

Lloyd's Register
Foundation

the arrangement of Valves and their connections such as to prevent the possibility of water passing from the sea or from water tanks into the
compartment to another Is the Shaft Tunnel watertight Is it fitted with a watertight door