

are subject to non-occurrence of Labour Disputes, Lock-Outs, Fire, Accidents, and other unforeseen contingencies.

PHIC ADDRESS,
ST HARTLEPOOL.

ERED OFFICE,
YARD, WEST HARTLEPOOL.

TELEPHONE SERVICE:

MIDDLETON SHIPYARD.		HARBOUR DOCK YARD.	
P.O.	Nº 4.	NATIONAL 1ST WIRE Nº	3.
NATIONAL 1ST WIRE	" 246	" 2ND " "	355.
" 2ND "	" 205		
" " "	" 206		
EMERGENCY " 398.			

Irvine's Ship Building & Dry Docks Co. Ltd

SHIP BUILDERS, ENGINEERS, REPAIRERS AND SALVORS.

MIDDLETON SHIPYARD AND THE HARBOUR DOCKYARD.

GRAVING DOCKS,
O AND 376 FEET LONG.

ENGINES AND SALVAGE
PLANT,
STEAMER "RECOVERY"

LOYDS REGISTER
LONDON
1 FEB 1915
5/2/15
p.c. W. H. H. West Hartlepool.

30th January 1915.

Messrs Lloyds Register of Shipping,

71 Fenchurch Street,

London E.C.

Dear Sirs,

T.S.S. No. 555.


RETAIN

We enclose herewith particulars of Freeboard for the above vessel, which we omitted to send you when submitting the Midship Section and Profile for approval, and shall be glad to have a preliminary assignment of freeboard at your earliest convenience.

Yours faithfully,

FOR IRVINE'S SHIP BUILDING & DRY DOCKS CO., LIMITED

A. B. Gordon
MANAGING DIRECTOR



© 2020

Lloyd's Register
Foundation

W383-0073

Indian Summer

N.A. Winter

Referred to the Chief Ship Surveyor

7K No

FEB 1 1915

REGISTERED

SHIPPING TO BEHOLD ABROAD

ON BOARD

REG. NO. 222

NO. 222

R

© 2020

Lloyd's Register
Foundation

Length
Beam
Depth
Length
Height
Sheer
Round
Under
Tonnage
Tonnage
Class
Bridge
to ton