



LLOYD'S REGISTER
LONDON.

REC'D DEC 2 1916
ANS2

Consultative Branch,

Board of Trade,

54, Victoria Street,

London, S.W.,

1st. December 1916.

S.S. "DUQUESA". Irvine's No. 555.

Sir,

RETAIN
The watertight subdivision of this passenger steamship has been under consideration, and has been approved for a subdivision load line corresponding to 29.1 feet moulded draught.

The freeboard to be assigned in accordance with the load line tables and marked upon the vessel's sides will therefore require to be considered in this connection and if necessary modified in order to comply with the condition laid down in paragraph 10 page 6 of the Board's Instructions relating to the Construction of Passenger Steamships, namely that none of the Statutory marks indicating the freeboard in salt water is to be placed in a higher position on the vessel's sides than the subdivision load line.

I am, Sir,

Your obedient servant,

W. David Archer

Principal Ship Surveyor.

The Chief Ship Surveyor,

Lloyd's Register.



© 2020

Lloyd's Register
Foundation

W383-0078

Referred to the Chief Ship Surveyor.

SM

DEC 12 1883

C. J. D.

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR

RECEIVED CHIEF SURVEYOR



© 2020

Lloyd's Register Foundation