

No. \_\_\_\_\_  
House \_\_\_\_\_

696-18

Deduct height of tween deck when this does not exceed 8ft.

Built at \_\_\_\_\_

Ship Surveyor 8.6.18

Received from Chief Ship Surveyor \_\_\_\_\_

ME Steel Twin  $\frac{1}{2}$ s Duquesa Rpt. Hpe No. 15499

of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1<sup>st</sup> entry.

It is submitted the Surveyors should be requested forward the approved plans showing the superstructures and arrangement of deep stringer & casings in way of machinery space, and at the same time they should state whether they are correct in reporting that the butts of Q strake are treble riveted.

RETAIN

Hpe 10/6/18



© 2020

Lloyd's Register  
Foundation

W383-0165

tion of the continuation of upper side of \_\_\_\_\_ at awning or pt.-awning dk.

ins.

1 1/2

Launched  
(S)  
S.B. 4  
LDER  
ok.)  
N.D.C.  
P.P.O.  
ry Do  
o. of D  
o. of T  
nd up  
k. Bea  
Inches  
a Ship  
L.V.L.  
3.07  
V.G.T.  
L.E.P.  
3 1/2