




Lloyd's Register of Shipping,

55, Fawcett Street,

Sunderland, 12th November, 1940.



ence
S.

Dear Sir,

In reply to your Classing letter of the 8th instant respecting the M.V. "FULTALA", S'land Report No. 32996, we beg to state the breadth of the bracket floors at the middle line should be 45" instead of 32½". In addition to the beams in way of the deck openings the through beams are 9 x 3½ x .38 B.A. and 10 x 32 x .44 B.A. at upper and second decks respectively. Cement has been laid in the double bottom tanks except in way of Nos. 4 and 5 oil fuel tanks.

We are, Dear Sir,

Yours faithfully,
THE SURVEYORS,
PER:

C. A. Miller

The Secretary,

WOKINGHAM.

Mr Dykes states a diff. between this vessel & the "Derwenthall" from G.W.



© 2020 Lloyd's Register of Shipping
Lloyd's Register
Foundation

W39-0201

W39-0202

14 NOV 1948

Lo
MT
[Signature]

MEMORANDUM

The Secretary

Confidential

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED

DATE 10/15/01 BY SP-6

TO : Mr. Tolson

FROM : Mr. E. A. Tamm

SUBJECT: [Illegible]

RE: [Illegible]

1. [Illegible]

2. [Illegible]

3. [Illegible]

4. [Illegible]

5. [Illegible]

© 2020

Lloyd's Register Foundation



CONFIDENTIAL

CONFIDENTIAL

CONFIDENTIAL